Division of Oil, Gas, & Mining Mining Report

10/20/92

MINE ID: M045017

MINE NAME: MERCUR MINE

OPERATOR: BARRICK MERCUR GOLD MINES, INC

CONTACT: GLENN M EURICK ADDRESS: P O BOX 838

TOOELE UT 84074

PHONE:

(801)268-4447

BLM #: Surface Owner: PRIVATE Lease #: Mineral Owner: PRIVATE

Town Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr1 Qtr-Qtr-Qtr2 Qtr-Qtr2 Qtr2 Sec Range 3.0W 6.0S 3.0W 6.0S

3.0W 5.08 32

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO, ACT, SUS, RET): ACT

Acreage:

892

Minerals Mined AU, AG

RECEIVED DATE DATE				
03/10/91 05/01/81 10/13/81 10/08/92				LAST INSPECTED
	03/10/81	05/01/81	10/13/81	10/08/92

BOND TYPE: SELF BOND

BOND AMOUNT: 8,808,891

ANNUAL REPORT YEAR: 91

	NONCOMPLIANCE NOTICES:	0	DATE ISSUED:	/	1	DATE RESOLVED:	1	1
I	VIOLATIONS:	0	DATE ISSUED:	1	1	DATE RESOLVED:	1	/
I	REVISIONS:	0	DATE REC'D:	1	1	DATE APPROVED:	1	1,
I	AMENDMENTS:	0	DATE REC'D:	/	1	DATE APPROVED:	/	/

COMMENTS:

INSPECTION MADE DURING THE RESEEDING OF THE SUNRISE WASTEROCK DUMP. THE SEEDING WAS BEING DONE BY HYROSEED METHOD USING A HOSE AND SEEDING FROM THE BOTTOM OF THE DUMP TO THE TOP. METHOD USED WAS QUITE EFFECTIVE. IT WOULD NOT BE AS EFFECTIVE ON A SLOPE LONGER THAN THE SUNRISE AS THE LENGTH OF THE HOSE WOULD BE TOO LARGE FOR MEN TO HANDLE.